10/695,965

PATENT

FEB 0 2 2006

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant	Maurice Anderson
Application No. 10/695,965	Filing Date: October 29, 2003
Patent No.	6,907,818 B2
Title of Application:	A System And Method For Providing Dry Filtered Air To A Brake Actuator
Confirmation No. 7998	Art Unit: 3745
Examiner	Michael S. Leslie

Commissioner for Patents Post Office Box 1450 Alexandria, VA 22313-1450

FEB 0 6 2006

Certificate

01925-P0225A WWW/CHS

of Correction

ATTENTION: Decision and Certificate of Correction

Branch of the Patent Issue Division

## Request for Certificate of Correction of Patent for Applicant's Mistake (37 CFR 1.323)

It is noted that an error appears in this patent of a typographical nature or character, as more fully described below. It occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination. A certificate of correction is requested.

Attached in duplicate is Form PTO-1050 with at least one copy being suitable for printing.

NOTE: Form PTO-1050, using the column and line number in the printed patent, should be used exclusively regardless of the length or complexity of the subject matter. MPEP §1485.

NOTE: The patent grant should be retained by the patentee. The PTO does not attach the certificate of correction to the patentee's copy of the patent. The patent grant will be returned to the patentee if submitted. MPEP §1485.

<u>Certificate of Mailing:</u> I hereby certify that this correspondence is today being deposited with the U.S. Postal Service as first class mail in an envelope addressed to: Commissioner for Patents; Post Office Box 1450; Alexandria, VA 22313-1450.

January 31, 2006

Lisa A. Evensen

02/03/2006 MWDLDGE1 00000077 6907818

01 FC:1811

100.00 OP

Page two
Patent No. 6,907,818  $\beta$ 2
Request for Certificate of Correction

The exact page and line number where the errors occur in the application filed October 29, 2003 are:

NOTE: This information should be identified in this request, however, on Form PTO-1050, only the column and line number in the printed patent should be used. MPEP §1485.

Page 16, Par. [00051], line 5.

Page 24, Claim 26, lines 2-3.

A check in the amount of \$100.00, as required by 37 CFR § 1.20(a), in payment of this fee. If there is any fee deficiency, please charge Account No. 19-4516.

Please send the Certificate to:

Name:

Wesley W. Whitmyer, Jr., Esquire

Address:

ST.ONGE STEWARD JOHNSTON & REENS LLC

986 Bedford Street

Stamford, Connecticut 06905

Respectfully submitted,

January <u>31</u>, 2006

Wesley W. Whitmyer, Jr., Registration No. 33,558

Attorneys for Applicant

ST.ONGE STEWARD JOHNSTON & REENS LLC

986 Bedford Street

Stamford, CT 06905-5619

203 324-6155

## UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,907,818 62

DATED : June 21, 2005

INVENTOR : Maurice Anderson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 8, lines 19-20:

"(SP)-[( $P_{108}$ )×( $A_2$ )]>( $P_{112}$ )×( $A_1$ )" should read -- (SP)-[( $P_{108}$ )×( $A_2$ )]>-( $P_{112}$ )×( $A_1$ ) --.

Col. 12, lines 43-45, Claim 26.

"F-[a pressure in the service chamber  $(P_{108})]\times(A_2)$ >[a pressure in the spring cavity  $(P_{112})]\times(A_1)$ " **should read --** F-[a pressure in the service chamber  $(P_{108})]\times(A_2)$ >-[a pressure in the spring cavity  $(P_{112})]\times(A_1)$  --.

-----

Mailing Address Of Sender:

Certificate of Correction (PTO Form 1050) - Amended

Wesley W. Whitmyer, Jr., Esquire ST.ONGE STEWARD JOHNSTON & REENS LLC

986 Bedford Street

Stamford, Connecticut 06905-5619

Patent No.: 6,907,818